

Message

From: Rumrill, Nancy [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=ECC4D19E0739473E8D3B141813288234-NRUMRILL]
Sent: 11/8/2018 6:46:53 PM
To: Dan Johnson [DanJohnson@florencecopper.com]
Subject: RE: Supplemental Well M57-O Bond Log Discussion

Hi Dan,

Are you and your consultant available at 12 pm PST or at 3:30 pm PST, today? I'm trying to coordinate a call with Jim Walker.

Thanks, Nancy

~~~~~  
Nancy Rumrill ([rumrill.nancy@epa.gov](mailto:rumrill.nancy@epa.gov))  
Drinking Water Protection Section (WTR-3-2)  
US EPA, Region IX  
75 Hawthorne St.  
San Francisco, CA 94105  
Phone (415) 972-3293

---

**From:** Dan Johnson <DanJohnson@florencecopper.com>  
**Sent:** Thursday, November 8, 2018 8:47 AM  
**To:** Rumrill, Nancy <Rumrill.Nancy@epa.gov>  
**Cc:** Albright, David <Albright.David@epa.gov>  
**Subject:** Supplemental Well M57-O Bond Log Discussion

Good Morning Nancy,

Per our conversation a few days ago, I have further reviewed the bond log index for Supplemental Well M57-O. I've attached the bond log itself and the bond index table with highlighted notes for your consideration. After my further review, I'm confident that the bond log index meets EPA's criteria (>80%) and it's especially good at the Middle Fine-Grained Unit/Lower Basin Fill Unit contact, throughout the MFGU and up into Upper Basin Fill Unit where it reaches over 99.8%. Please review the attached information and call me if further discussions or information is needed.

Best Regards,

**Dan Johnson** VP | General Manager



Florence Copper Inc.  
1575 W. Hunt Highway Florence AZ USA 85132  
C 520-233-1930 T 520-374-3984 F 520-374-3999  
E [danjohnson@florencecopper.com](mailto:danjohnson@florencecopper.com) Web [florencecopper.com](http://florencecopper.com)

---

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."